

Message

From: Dan Womer [dwomer@nfrfc.org]
Sent: 9/11/2019 12:40:29 PM
To: Steele, Mariah [Steele.Mariah@epa.gov]
CC: NFRC IVP [ivp@nfrfc.org]; 'enforcement@icfi.com' [enforcement@icfi.com]
Subject: RE: FAILURE: Marvin Windows and Doors / Clad Outswing French Door IZ (BBNM) - 16-024-01.01

Hi Mariah,

I would like to hop on a quick call to discuss this topic. We've spoken with Marvin about this and they feel it's unnecessary to do another test on the product.

The reason they feel it's unnecessary is because they do not label that specific product option for ENERGY STAR® anymore. When they recertified the product line earlier this year chose to no longer label the product for NFRC.

I spoke with them on the phone and told them that although that specific product option is no longer being labeled, likely there will still need to be a test of a product from the product line MAR-N-112. I'll forward you the discussion we had via email after that call.

Please let me know when you're available to chat. I hope it won't take more than 15 minutes or so.

Thanks,

Dan Womer
Program Administrator

National Fenestration Rating Council, Inc. (NFRC)

Office: (301) 589-1776

Direct: (240) 821-9510

Celebrating 30 years of Fair, Accurate and Credible Ratings

[Twitter](#) | [Facebook](#) | [LinkedIn](#)

STATEMENT OF CONFIDENTIALITY

The information contained in this electronic message and any attachments to this message are intended for the exclusive use of the addressee(s) and may contain confidential or privileged information. If you are not the intended recipient, please notify NFRC immediately at either 301-589-1776 or at info@nfrfc.org, and destroy all copies of this message and any attachments.

From: ENERGY STAR Enforcement <enforcement@icfi.com>
Sent: Monday, July 1, 2019 2:20 PM
To: Dan Womer <dwomer@nfrfc.org>
Cc: NFRC IVP <ivp@nfrfc.org>
Subject: Re: FAILURE: Marvin Windows and Doors / Clad Outswing French Door IZ (BBNM) - 16-024-01.01

Dear Dan Womer:

Because of lab and report irregularities associated with **Marvin Windows and Doors MAR-N-112-16848-00001**, EPA is authorizing a retest of this product to U-Factor requirements. Once the retest has been completed, please send confirmation and a new failure report if necessary to Enforcement@energystar.gov.

Sent on behalf of:

Mariah Steele

ENERGY STAR Partner Accountability

U.S. Environmental Protection Agency

(202) 343-9305

Email: Steele.Mariah@epa.gov

From: Dan Womer <dwomer@nfrc.org>

Sent: Thursday, February 8, 2018 1:42 PM

To: 'tdeonauth@drintl.com'

Cc: NFRC IVP; ENERGY STAR Enforcement

Subject: FAILURE: Marvin Windows and Doors / Clad Outswing French Door IZ (BBNM) - 16-024-01.01

Hello,

Please find attached the Energy Star Verification Testing Failure Report for Marvin Windows and Doors / Clad Outswing French Door IZ (BBNM) / MAR-N-112-16848-00001.

Thank you,

Dan Womer

Program Administrator

National Fenestration Rating Council

6305 Ivy Lane, Suite 140

Greenbelt, MD 20770

Phone: 240-821-9510

Fax: 301-589-3884

NFRC Website | NFRC News Now

STATEMENT OF CONFIDENTIALITY

The information contained in this electronic message and any attachments to this message are intended for the exclusive use of the addressee(s) and may contain confidential or privileged information. If you are not the intended recipient, please notify NFRC immediately at either 301-589-1776 or at info@nfrf.org, and destroy all copies of this message and any attachments.